

EXHIBIT F

East Forsyth HS

Approved

ECI C O #	C O Date	Description	Amount	GC C O #	Approval Date
1903-01RA	11/1/2019	ECI to make changes to contract drawings per ASI #1.	\$ 10,554.00	#1	
1903-02	8/5/2019	ECI to make changes to contract drawings per ASI #3.	\$ 1,381.00	#1	
1903-06	11/11/2019	ECI to extend the feeder conduits and fire alarm conduits for the Stadium restrooms and the visitor restrooms per PR#2.	\$ 1,719.00	#2	12/2/2019
1903-04	8/26/2019	ECI to provide connections to 4 smoke vents above stage per RFI #30.	\$ 1,369.00	#3	12/9/2019
1903-09	1/3/2020	ECI to give credit for controller wires and conduit per ASI002.	\$ (326.00)	#4	2/25/2020
1903-11	2/6/2020	ECI to provide a credit for not installing the second conduit from the data box to the cable tray in area's four and five on both levels.	\$ (5,100.00)	#5	4/10/2020
1903-BC9	6/26/20	CDCC Furished Firecaulk	\$ (2,328.39)	#6	6/26/2020
1903-10R	4/15/2020	ECI to provide power tie in for the coiling door at door 1500C per ASI #025.	\$ 989.00	#7	6/22/2020
1903-20	6/18/2020	We are pleased to offer pricing to install a 2" conduit from the baseball concessions to the septic pump house with a pull string.	\$ 3,073.00	#8	7/20/2020
1903-12	3/23/2020	ECI to provide 208v circuits to (3) boilers per RFI 0095.	\$ 563.00	#9	
1903-16	6/10/2020	ECI is pleased to provide power to electric heater per RFI #109 response.	\$ 1,782.00	#9	
1903-18	6/10/2020	ECI to provided additional type OF lights and type OG lights per ASI #39.	\$ 84,739.00	#9	
1903/19	6/18/2020	We are pleased to offer pricing to add a receptacle for a drinking fountain as reviewed in RFI-116. Wall is already built, so a new box has to be cut into the wall.	\$ 975.00	#9	
1903-21R	6/24/2020	ECI to provide additional data drops per the email from the GC on 06/05/20.	\$ 4,646.00	#9	
1903-14RA	6/26/2020	ECI to make changes FA changes per ASI 026. ECI cannot flush mount in any completed CIP walls. Tennis Court Lighting excluded.	\$ 7,943.00	#9	
1903-17RA	7/15/2020	ECI is to provide power for the range hoods associated with RFI #110 response.	\$ 667.00	#9	
1903-BC1	8/28/2020	Backcharge for gas line that was hit	\$ (2,690.00)	#10	
1903-BC2	8/31/2020	Backcharge for damage to ERU's	\$ (68,148.66)	#11	
1903-BC3	9/2/2020	Backcharge for gas line that was hit	\$ (1,943.00)	#12	
1903-BC4	9/8/2020	Backcharge for gas line that was hit	\$ (4,269.00)	#13	
1903-BC5	10/15/2020	Current Clean Up of Unidentifiable and Dirt / Mud	\$ (10,000.00)	#14	



1903-08R	1/3/2020	ECI to provide NEZDP433 smoke rated sleeves where the cable tray penetrates smoke rated walls and three 3 inch conduits where the tray passes thru non-rated walls.	\$ (143.00)	#15	10/23/2020
1903-15	5/20/2020	ECI to make changes per ASI 035.	\$ 341.00	#15	10/23/2020
1903-23	7/2/2020	ECI to supply cabling and circuit changes per ASI 041.	\$ 3,182.00	#15	10/23/2020
1903-24	7/15/2020	ECI to raise outlet boxes in masonry wall in the kitchen per RFI Response #0125.	\$ 882.00	#15	10/23/2020
1903-26	9/25/2020	ECI to provide PA speakers and WAP's to the construction tech building per ASI #53.	\$ 6,263.00	#15	10/23/2020
1903-BC6	12/9/2020	Backcharge for boom Lifts	\$ (6,800.00)	#16	
1903-28	11/9/2020	ECI to provide circuit for added heat trace per RFI #0162 response	\$ 681.00	#17	2/11/20
1903-31	12/9/2020	ECI to make changes to gym curtain power per RFI Response #167	\$ 1,487.00	#17	2/11/2020
1903-BC5	2/11/2020	Damage for ERU Penetrations	\$ 6,272.50	#17	
1903-29	11/11/2020	ECI to provide a 480v control circuit to each control cabinet (Baseball & Football) as required by Musco, in addition to the 277v control already shown in the panel schedules.	\$ 1,603.00	#18	1/29/2021
1903-37	1/25/2021	ECI to provide circuitry to exhaust fans per response to Question #1 of RFI #176.	\$ 1,040.00	#18	2/12/2021
1903-38	1/25/2021	ECI to provide PA shutdown interface by Fire Alarm per RFI response #176 item #2.	\$ 1,893.00	#18	2/12/2021
1903-41	1/29/2021	ECI to provide additional data drops to Mech Rm, Cooler/Freezer, Elevators & Wheelchair lift by Elevator #1.	\$ 7,115.00	#18	2/12/2021
1903-39R	2/3/2021	ECI to provide transformer for ALIC panel at the Baseball field. ALIC panel requires 120V EMG power and the only power at this location is 277/480V.	\$ 1,920.00	#18	2/12/2021
1903-BC7	2/12/2021	Theater Slab Repairs	\$ (14,127.00)	#18	2/12/2021
1903-40	1/29/2021	ECI to make accomodations for ansul system at Pizza oven per RFI #173 response.	\$ 1,930.00	#19	4/5/2021
1903-32	12/9/2020	ECI to provide circuitry to water heaters as noted in RFI #169 response.	\$ 1,971.00	#20	5/10/2021
1903-36R	1/22/2021	ECI to provide homerun circuits to (3) exhaust fans at welders and power for the louvers per RFI 0172.	\$ 3,100.00	#20	5/10/2021
1903-42	2/19/2021	ECI to provide additional circuitry to plumbing equipment and sprinkler compressor per ASI #58.	\$ 3,881.00	#20	5/10/2021
1903-BC10	5/10/2021	EPDM on parapet wall at weight room roof due to conduit on parapet	\$ (4,895.00)	#20	5/10/2021
1903-BC11	5/25/2021	RTU Replacment (27 Units)	\$ (758,336.51)	#21	5/25/2021
1903-BC14		Backcharge for misc. ceiling and sheetrock repairs	\$ (18,596.00)	#22	5/28/2021

1903-35	1/8/2021	ECI to provide circuitry to basketball shot clocks and intercept power to scoreboards and shot clocks to be controlled via switch installed adjacent to goal hoist switches.	\$ 8,247.00	#24	6/18/2021
1903-BC12		BC for State Elevator Re-inspection fee	\$ (5,500.00)	#24	6/18/2021
1903-51	5/11/2021	Shunt trip breaker and controls for elevator.	\$ 5,355.00	#25	8/6/2021
1903-60RA	6/8/2021	Add and relocate Cord reel and receptacles per ASI#60	\$ 12,801.00	#25	8/6/2021
1903-BC13	8/6/2021	Damaged Site Utility Lines	\$ (2,798.11)	#25	8/6/2021
1903-66	8/20/2021	ECI to provide a quad receptacle at the bleachers on each side of football field at the 50 yard line.	\$ 4,658.27	#26	10/5/2021
1903-62	6/23/2021	the freezer man to rebuild panels. We started to reinstall lights and were asked to stop because	\$ 5,532.00	#27	10/6/2021
1903-33	12/23/2020	ECI had to troubleshoot and repair (3) 4" and (2) 1.25" conduits that were damaged by the power company's installation of primary conductors. We were not notified of damages and had to find them.	\$ 1,864.00	#28	10/28/2021
1903-43	3/1/2021	ECI to provide relay and smoke detectors for coiling smoke door at Prop Room 1670 on page ET-131.	\$ 1,524.00	#28	10/28/2021
1903-44	3/12/2021	ECI to provide smoke detector at elevator penthouse per RFI #177 response to question #1.	\$ 644.00	#28	10/28/2021
1903-45	3/16/2021	ECI to provide power for EWC's in corridor 2000 pg Ep-136 per RFI #177 response to question #2.	\$ 2,218.00	#28	10/28/2021
1903-47	5/11/2021	Relocated receptacle in sheetrock wall from eighteen inches to forty eight inches.Room 1015 sequence B.	\$ 238.00	#28	10/28/2021
1903-48	5/11/2021	Relocated receptacle in sheetrock wall from eighteen to forty eight inches.Room 1030 Sequence B.	\$ 238.00	#28	10/28/2021
1903-50	5/11/2021	Circuitry for four TPDU's (trap primer) in corridor #1700 outside of toilet room 1716 EP-126, in room 3005 EZ-1002, in room 4082 (EX-101), and room 4072 (EX-101).	\$ 1,386.00	#28	10/28/2021
1903-52	5/11/2021	Rewiring of equipment in kitchen that was supplied as 208V, but the prints called for 120V. Items #67, 58 and 71.	\$ 969.00	#28	10/28/2021
1903-55	5/11/2021	Backcharge for damages to Fire Alarm panel when the county drilled holes into the enclosure	\$ 1,344.00	#28	10/28/2021
1903-56	5/12/2021	Two exit lights were added on the second floor in sequence four in the main corridor per the Fire Marshal.	\$ 1,055.00	#28	10/28/2021
1903-57	5/13/2021	Added Smoke detector in laptop storage room at owners request.	\$ 449.00	#28	10/28/2021
1903-63	8/3/2021	Per James, ECI is adding a dedicated circuit for the Coke machine in the concessions in the gym.	\$ 2,300.00	#28	10/28/2021
1903-69	9/29/2021	ECI to add raceways for the scoreboard control cables.	\$ 1,272.00	#28	10/28/2021
1903-68	9/20/2021	ECI to replace and certify fieldhouse FA panel that was destroyed be a lighting strike.	\$ 8,450.00	#29	11/3/2021
1903-27	10/28/2020	ECI to re-feed Boiler pumps P5, P6 & P7 from a 208v panel to match pumps that were installed.	\$ 1,910.00	#30	11/4/2021
1903-46	5/11/2021	Circuitry for four different dry system sprinkler air compressors. Found in mech corridor 2115, 2520,2506 and 1420.	\$ 518.00	#30	11/4/2021

1903-49	5/11/2021	Circuitry and connections to dishwasher solenoid.	\$ 659.00	#30	11/4/2021
1903-54	5/11/2021	Backcharge from Southern Signal for damage caused by HVAC condensation leakage	\$ 1,216.00	#30	11/4/2021
1903-58	5/21/2021	Replacement of Fire Alarm devices damaged by water from sprinkler pressure test.	\$ 2,860.00	#30	11/4/2021
1903-59	5/28/2021	ECI removed and re-installed 13 recessed can lights in sheetrock ceiling due to roof leak above cafeteria.	\$ 1,699.00	#30	11/4/2021
1903-64	8/16/2021	ECI repaired conduit and repulled wire between section 1 and 4 that was damaged by the grader.	\$ 3,708.00	#30	11/4/2021
1903-65	8/16/2021	ECI repaired conduit and wire for Tennis court pole lights that was damaged by the grader.	\$ 1,177.00	#30	11/4/2021
1903-70	11/4/2021	Credit for RTU work	\$ 93,401.00	#30	11/4/2021